

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002621**Date Inspected:** 19-May-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 2300**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 800**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** An Qing Xiang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower & OBG**Summary of Items Observed:**

The Caltrans Quality Assurance (QA) Inspector Charlie Franco was present at the time requested to randomly observe welding and associated operations being performed for the Tower and Orthotropic Box Girders (OBG).

New Tower Shop Bay 1:

The QA Inspector randomly observed ZPMC welder Xu Yan ID Number 052917, utilizing the Submerged Arc Welding (SAW) Process in the 1G Position (Flat Groove) with ZPMC Weld Procedure Specification (WPS) WPS-B-T-2221-B-U3c-S, to weld the fill pass in Weld Joint (WJ) SSD1-SA179B/E-3A on Tower Skin Plate C Sub-Assembly SA179(S) piece marks p69(S) to p84(S). The QA Inspector randomly observed ZPMC CWI An Qing Xiang monitoring weld parameters. The QA Inspector also randomly monitored weld parameters and recorded them as follows: 692 amps, 33.6 volts with a travel speed of 620 millimeters (mm) per minute. The weld parameters appeared to comply with contract requirements. The attached photograph provides additional detail.

The QA Inspector randomly observed ZPMC welder Xu Xuishui ID Number 040489, utilizing the SAW Process in the 1G Position (Flat Groove) with ZPMC WPS WPS-B-T-2221-B-U3c-S, to weld the fill pass in WJ SSD1-SA179B/E-2A on Tower Skin Plate C Sub-Assembly SA179(S). The QA Inspector randomly observed ZPMC CWI An Qing Xiang monitoring weld parameters. The QA Inspector also randomly monitored weld parameters and recorded them as follows: 666 amps, 32.9 volts with a travel speed of 623 mm per minute. The weld parameters appeared to comply with contract requirements. The attached photograph provides additional detail.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)




New Tower Shop Bay 2:

The QA Inspector randomly observed ZPMC welder Cao Xiahua ID Number 056975, utilizing the SAW Process in the 1G Position (Flat Groove) with ZPMC WPS WPS-B-T-2221-B-U3c-S, to weld the fill pass in WJ ESD1-SA49C/D-18B(CJP), -7(PJP), -9B(CJP) and -11(PJP) on Tower Skin Plate B Sub-Assembly SA49(E). The QA Inspector randomly observed ZPMC CWI An Qing Xiang monitoring weld parameters. The QA Inspector also randomly monitored weld parameters and recorded them as follows: 666 amps, 33.7 volts with a travel speed of 620 mm per minute. Weld parameters were recorded for WJ ESD1-SA49C/D-18B. The weld parameters appeared to comply with contract requirements. The attached photograph provides additional detail.

The QA Inspector randomly observed ZPMC welder Shen Mei ID Number 041716, utilizing the SAW Process in the 1G Position (Flat Groove) with ZPMC WPS WPS-B-T-2221-B-U3c-S, to weld the fill pass in WJ ESD1-SA49C/D-12B(CJP), -14(PJP), -15B(CJP) and -17(PJP) on Tower Skin Plate B Sub-Assembly SA49(E). The QA Inspector randomly observed ZPMC CWI An Qing Xiang monitoring weld parameters. The QA Inspector also randomly monitored weld parameters and recorded them as follows: 675 amps, 33.6 volts with a travel speed of 620 mm per minute. Weld parameters were recorded for WJ ESD1-SA49C/D-14B. The weld parameters appeared to comply with contract requirements. The attached photograph provides additional detail.

New Tower Shop Bay 3:

The QA Inspector observed no welding or other contract work being performed at this location.



WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Summary of Conversations:

There were no relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Franco,Charlie	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer
